



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

ORGANIZATION: 3-BAY COUNTY SCHOOL DISTRICT

FACILITY: CALLAWAY ELEMENTARY

FACILITY USE: ALL

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

FACILITY: 5-A CALLAWAY ELEMENTARY

Primary Use: ELEMENTARY

Grades Housed: PK - 05

DOE Validation Date:

Capital Outlay Classification: SCHOOL RECOMMENDED FOR CONTINUED USE

MASTER SCHOOL ID

MSID	Name	Status
101	CALLAWAY ELEMENTARY SCHOOL	Default

CAPITAL OUTLAY FTE

Year: 2017 / 2018							
PK: 6.08	01: 73.00	03: 101.50	05: 59.50	07: 0.00	09: 0.00	11: 0.00	PK-12: 507.24
KG: 80.50	02: 96.66	04: 90.00	06: 0.00	08: 0.00	10: 0.00	12: 0.00	Adult: 0.00
							Total: 507.24

SCHOOL CAPACITY

SCHOOL CAPACITY	YEAR ROUND CAPACITY	UTILIZATION FACTOR	PRIMARY USE
898	1,078	1.00	ELEMENTARY

PARCEL: 6

7115 HIGHWAY 22

PANAMA CITY, FL 32404

Parking: DEVELOPED	Owner: SCHOOL BOARD	Fire: 6
Athletic: NO ATHLETIC FACILITY	Water: PUBLIC	Police: COMBINATION
Sewage: PUBLIC	Plan: COMBINATION OF 1-7	Drainage: ADEQUATE
Landscape: DEVELOPED	Playground: INCLUDED WITH SITE	Acreage: 20.00
Date Acquired: 1/1/1936		Lease Expiration Date:



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 1 - Building Number 00001

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: GAS
Year Constructed: 1981	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified: 2013	Educational TV: CLOSED CIRCUIT	Heat Capacity: ADEQUATE
Average Age NSF: 1982	Intercom: TWO WAY COMPLETE	Walls: BRICK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: DOUBLE INSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
100	263	304	RECEPTION AREA	0	01	CARPET	1981	SATISFACTORY	1	6	5
100A	231	300	PRINCIPAL/DIRECTOR OFFICE	0	01	CARPET	1981	SATISFACTORY	1	6	5
100B	151	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	CARPET	1981	SATISFACTORY	1	6	5
100C	179	303	SECRETARIAL SPACE	0	01	CARPET	1981	SATISFACTORY	1	6	5
100D	75	308	GENERAL SCHOOL STORAGE	0	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
100E	66	317	GENERAL SCHOOL SPACE	0	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
100F	42	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1981	SATISFACTORY	1	6	5
100G	138	307	CLINIC	0	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
100H	46	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1981	SATISFACTORY	1	6	5
100J	108	302	BOOKKEEPING OFFICE	0	01	CARPET	1981	SATISFACTORY	1	6	5
100K	151	306	CONFERENCE ROOM	0	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 1 - Building Number 00001

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
100L	141	309	VAULT/STUDENT RECORDS	0	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
100M	31	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	01	COMPOSITION TILE	2013	SATISFACTORY	1	6	5
100N	31	331	CUSTODIAL SERVICE CLOSET	0	01	COMPOSITION TILE	2013	SATISFACTORY	1	6	5
100O	133	304	RECEPTION AREA	0	01	COMPOSITION TILE	2013	SATISFACTORY	1	6	5
101	48	316	TEACHER LOUNGE/DINING	0	01	COMPOSITION TILE	2013	SATISFACTORY	1	6	5
102	990	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
102A	44	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1981	SATISFACTORY	1	6	5
102B	43	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
102C	33	702	MECHANICAL ROOM	0	01	COMPOSITION TILE	2013	SATISFACTORY	1	6	5
103	993	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
103A	50	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1981	SATISFACTORY	1	6	5
103B	44	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
103C	33	702	MECHANICAL ROOM	0	01	COMPOSITION TILE	2013	SATISFACTORY	1	6	5
104	993	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
104A	45	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1981	SATISFACTORY	1	6	5
104B	43	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
104C	33	702	MECHANICAL ROOM	0	01	COMPOSITION TILE	2013	SATISFACTORY	1	6	5
105	978	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
105A	54	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1981	SATISFACTORY	1	6	5



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 1 - Building Number 00001

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
105B	44	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
105C	33	702	MECHANICAL ROOM	0	01	COMPOSITION TILE	2013	SATISFACTORY	1	6	5
106	1016	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
106A	44	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1981	SATISFACTORY	1	6	5
106B	43	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
106C	33	702	MECHANICAL ROOM	0	01	COMPOSITION TILE	2013	SATISFACTORY	1	6	5
107	991	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
107A	50	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1981	SATISFACTORY	1	6	5
107B	43	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
107C	33	702	MECHANICAL ROOM	0	01	COMPOSITION TILE	2013	SATISFACTORY	1	6	5
108	1098	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1981	SATISFACTORY	1	6	5
109	33	702	MECHANICAL ROOM	0	01	CONCRETE	1981	SATISFACTORY	1	6	5
110	1241	701	COVERED WALKWAY	0	01	CONCRETE	1981	SATISFACTORY	1	6	5

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	10,912	108	0	0				
TOTAL	10,912	108	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 2 - Building Number 00002

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: GAS
Year Constructed: 1981	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT WATER
Year Modified: 2012	Educational TV: CLOSED CIRCUIT	Heat Capacity: ADEQUATE
Average Age NSF: 1982	Intercom: TWO WAY COMPLETE	Walls: BRICK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: DOUBLE INSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
200	956	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1981	SATISFACTORY	2	6	5
200A	44	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1981	SATISFACTORY	2	6	5
200B	44	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
200C	33	702	MECHANICAL ROOM	0	01	CONCRETE	2012	SATISFACTORY	2	6	5
201	916	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1981	SATISFACTORY	2	6	5
201A	44	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
201B	66	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
201C	33	702	MECHANICAL ROOM	0	01	CONCRETE	1981	SATISFACTORY	2	6	5
201D	85	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2012	SATISFACTORY	2	6	5
202	1018	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1981	SATISFACTORY	2	6	5
202A	49	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 2 - Building Number 00002

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
202B	66	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
202C	33	702	MECHANICAL ROOM	0	01	CONCRETE	2012	SATISFACTORY	2	6	5
203	998	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
203A	44	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
203B	66	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
203C	33	702	MECHANICAL ROOM	0	01	CONCRETE	2012	SATISFACTORY	2	6	5
204	68	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1981	SATISFACTORY	2	6	5
205	145	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
206	997	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1981	SATISFACTORY	2	6	5
206A	44	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
206B	67	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
206C	33	702	MECHANICAL ROOM	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
206D	85	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2012	SATISFACTORY	2	6	5
207	1031	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1981	SATISFACTORY	2	6	5
207A	38	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
207B	44	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
207C	33	702	MECHANICAL ROOM	0	01	CONCRETE	2012	SATISFACTORY	2	6	5
208	998	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	CARPET	1981	SATISFACTORY	2	6	5
208A	48	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 2 - Building Number 00002

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
208B	44	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
208C	33	702	MECHANICAL ROOM	0	01	CONCRETE	2012	SATISFACTORY	2	6	5
209	998	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	1981	SATISFACTORY	2	6	5
209A	44	814	STUDENT RESTROOM (BOTH SEXES)	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
209B	66	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
209C	33	702	MECHANICAL ROOM	0	01	CONCRETE	2012	SATISFACTORY	2	6	5
210	1107	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1981	SATISFACTORY	2	6	5
211	184	808	MATERIAL STORAGE	0	01	CONCRETE	1981	SATISFACTORY	2	6	5
212	160	702	MECHANICAL ROOM	0	01	CONCRETE	1981	SATISFACTORY	2	6	5

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	10,828	152	0	0				
TOTAL	10,828	152	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 3 - Building Number 00003

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1950	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified: 2000	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1951	Intercom: ONE WAY COMPLETE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: NONE	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
301	2942	340	DINING AREA	0	01	TERRAZZO	1950	SATISFACTORY	3	6	5
303	47	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	2013	SATISFACTORY	3	6	5
304	70	317	GENERAL SCHOOL SPACE	0	01	COMPOSITION TILE	2013	SATISFACTORY	3	6	5
305	426	316	TEACHER LOUNGE/DINING	0	01	COMPOSITION TILE	1950	SATISFACTORY	3	6	5
306	1616	346	KITCHEN FOOD PREPARATION	0	01	QUARRY TILE	1950	SATISFACTORY	3	6	5
307	50	820	STAFF RESTROOM (FEMALE)	0	01	CERAMIC TILE	1950	SATISFACTORY	3	6	5
308	263	350	OTHER FOOD SERVICE	0	01	COMPOSITION TILE	1950	SATISFACTORY	3	6	5
310	72	343	KITCHEN OFFICE	0	01	COMPOSITION TILE	1950	SATISFACTORY	3	6	5



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 3 - Building Number 00003

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
311	371	342	KITCHEN DRY STORAGE	0	01	CONCRETE	1950	SATISFACTORY	3	6	5
313	60	702	MECHANICAL ROOM	0	01	CONCRETE	1950	SATISFACTORY	3	6	5
314	50	808	MATERIAL STORAGE	0	01	CONCRETE	1950	SATISFACTORY	3	6	5
315	336	350	OTHER FOOD SERVICE	0	01	CONCRETE	1950	SATISFACTORY	3	6	5

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	6,303	0	0	0				
TOTAL	6,303	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 4 - Building Number 00004

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: ELECTRIC
Year Constructed: 1953	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified: 2000	Educational TV: CLOSED CIRCUIT	Heat Capacity: ADEQUATE
Average Age NSF: 1953	Intercom: ONE WAY COMPLETE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
401	24	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1953	SATISFACTORY	4	6	5
402	960	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1953	SATISFACTORY	4	6	5
403	960	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1953	SATISFACTORY	4	6	5
404	940	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1953	SATISFACTORY	4	6	5
404A	15	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1953	SATISFACTORY	4	6	5
405	864	701	COVERED WALKWAY	0	01	CONCRETE	1953	SATISFACTORY	4	6	5

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	3,763	66	0	0				
TOTAL	3,763	66	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 5 - Building Number 00005

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: COMBINATION OF 1-3
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1964	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified: 2000	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1967	Intercom: TWO WAY COMPLETE	Walls: CONCRETE
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
500	176	816	STUDENT RESTROOM (FEMALE)	0	01	CERAMIC TILE	1964	SATISFACTORY	5	6	5
502	858	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1964	SATISFACTORY	5	6	5
502A	16	702	MECHANICAL ROOM	0	01	CERAMIC TILE	1964	SATISFACTORY	5	6	5
503	858	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1964	SATISFACTORY	5	6	5
503A	16	702	MECHANICAL ROOM	0	01	CERAMIC TILE	1964	SATISFACTORY	5	6	5
504	858	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1964	SATISFACTORY	5	6	5
504A	16	702	MECHANICAL ROOM	0	01	CERAMIC TILE	1964	SATISFACTORY	5	6	5
505	858	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1964	SATISFACTORY	5	6	5



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 5 - Building Number 00005

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
505A	16	702	MECHANICAL ROOM	0	01	CERAMIC TILE	1964	SATISFACTORY	5	6	5
508	108	13	ELEMENTARY P E STORAGE	0	01	CONCRETE	1964	SATISFACTORY	5	6	5
509	276	314	ITINERANT OFFICE	0	01	COMPOSITION TILE	1964	SATISFACTORY	5	6	5
510	756	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1964	SATISFACTORY	5	6	5
511	936	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1964	SATISFACTORY	5	6	5
512	936	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	1964	SATISFACTORY	5	6	5
513	936	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1964	SATISFACTORY	5	6	5
514	176	815	STUDENT RESTROOM (MALE)	0	01	CERAMIC TILE	1964	SATISFACTORY	5	6	5
515	120	702	MECHANICAL ROOM	0	01	CONCRETE	1964	SATISFACTORY	5	6	5
517	230	300	PRINCIPAL/DIRECTOR OFFICE	0	01	COMPOSITION TILE	1964	SATISFACTORY	5	6	5
518	202	383	AUDIO VISUAL STORAGE	0	01	COMPOSITION TILE	1964	SATISFACTORY	5	6	5
519	450	387	MEDIA PRODUCTION LAB	0	01	COMPOSITION TILE	1964	SATISFACTORY	5	6	5
520	6651	380	LIBRARY (READING ROOM/STACKS)	0	01	CARPET	1964	SATISFACTORY	5	6	5
521	98	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	01	COMPOSITION TILE	1964	SATISFACTORY	5	6	5
522	3680	701	COVERED WALKWAY	0	01	CONCRETE	1980	SATISFACTORY	5	6	5

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	19,227	160	0	0				
TOTAL	19,227	160	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 6 - Building Number 00006

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1964	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1964	Intercom: ONE WAY COMPLETE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
600	900	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1964	SATISFACTORY	6	6	5
600A	25	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1964	SATISFACTORY	6	6	5
601	870	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1964	SATISFACTORY	6	6	5
601A	25	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1964	SATISFACTORY	6	6	5
603	440	701	COVERED WALKWAY	0	01	CONCRETE	1964	SATISFACTORY	6	6	5

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	2,260	36	0	0				
TOTAL	2,260	36	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 8 - Building Number 00008

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: NONE
Year Constructed: 1972	Artificial Lighting: NONE	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 1972	Intercom: NONE	Walls: WOOD
Relocatable Units: 0	Telephone: NONE	Struct Comp: WOOD
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
100	72	13	ELEMENTARY P E STORAGE	0	01	CONCRETE	1972	SATISFACTORY	8	6	5

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	72	0	0	0				
TOTAL	72	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 9 - Building Number 00009

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1976	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1976	Intercom: ONE WAY COMPLETE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
100	2100	121	OTHER P E SPACE	0	01	CONCRETE	1976	SATISFACTORY	9	6	5
102	502	13	ELEMENTARY P E STORAGE	0	01	CONCRETE	1976	SATISFACTORY	9	6	5

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	2,602	0	0	0				
TOTAL	2,602	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 10 - Building Number 00010

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1999	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1999	Intercom: TWO WAY COMPLETE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: COMPLETE TO ALL ROOMS	Struct Comp: CONCRETE
Stories: 1		Corridor: SINGLE INSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
000A	56	819	STAFF RESTROOM (MALE)	0	01	COMPOSITION TILE	1999	SATISFACTORY	10	6	5
000B	146	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1999	SATISFACTORY	10	6	5
001	505	315	TEACHER PLANNING OFFICE	0	01	COMPOSITION TILE	1999	SATISFACTORY	10	6	5
002	672	62	E S E FULL-TIME	10	01	COMPOSITION TILE	1999	SATISFACTORY	10	6	5
002A	156	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1999	SATISFACTORY	10	6	5
003	480	40	RESOURCE ROOM	0	01	COMPOSITION TILE	1999	SATISFACTORY	10	6	5
003A	90	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1999	SATISFACTORY	10	6	5
004	480	40	RESOURCE ROOM	0	01	COMPOSITION TILE	1999	SATISFACTORY	10	6	5



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 10 - Building Number 00010

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
005	40	702	MECHANICAL ROOM	0	01	CONCRETE	1999	SATISFACTORY	10	6	5
006	480	40	RESOURCE ROOM	0	01	COMPOSITION TILE	1999	SATISFACTORY	10	6	5
007	54	702	MECHANICAL ROOM	0	01	CONCRETE	1999	SATISFACTORY	10	6	5
008	64	702	MECHANICAL ROOM	0	01	CONCRETE	1999	SATISFACTORY	10	6	5
009	104	703	ELECTRICAL ROOM	0	01	CONCRETE	1999	SATISFACTORY	10	6	5
010	44	331	CUSTODIAL SERVICE CLOSET	0	01	CONCRETE	1999	SATISFACTORY	10	6	5
011	2480	701	COVERED WALKWAY	0	01	CONCRETE	1999	SATISFACTORY	10	6	5

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	5,851	10	0	0				
TOTAL	5,851	10	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 11 - Building Number 00011

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1999	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: COMBINATION OF 1-8	Heat Capacity: ADEQUATE
Average Age NSF: 1999	Intercom: TWO WAY COMPLETE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: COMPLETE TO ALL ROOMS	Struct Comp: CONCRETE
Stories: 1		Corridor: SINGLE INSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
100	1820	55	MUSIC - ELEMENTARY	0	01	CARPET	1999	SATISFACTORY	11	6	5
100A	155	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1999	SATISFACTORY	11	6	5
100B	70	831	MUSIC PRACTICE ROOM	0	01	CARPET	1999	SATISFACTORY	11	6	5
100C	70	806	REFERENCE	0	01	CARPET	1999	SATISFACTORY	11	6	5
101	1036	50	ART - ELEMENTARY	0	01	COMPOSITION TILE	1999	SATISFACTORY	11	6	5
101A	155	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1999	SATISFACTORY	11	6	5
101B	150	812	PROJECT STORAGE	0	01	COMPOSITION TILE	1999	SATISFACTORY	11	6	5
101C	60	805	KILN	0	01	CONCRETE	1999	SATISFACTORY	11	6	5
102	750	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1999	SATISFACTORY	11	6	5
102A	90	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1999	SATISFACTORY	11	6	5
102B	40	813	STUDENT STORAGE	0	01	COMPOSITION TILE	1999	SATISFACTORY	11	6	5



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 11 - Building Number 00011

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
102C	35	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1999	SATISFACTORY	11	6	5
103	50	811	OUTSIDE STORAGE	0	01	CONCRETE	1999	SATISFACTORY	11	6	5
104	950	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1999	SATISFACTORY	11	6	5
104A	155	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1999	SATISFACTORY	11	6	5
104B	40	813	STUDENT STORAGE	0	01	COMPOSITION TILE	1999	SATISFACTORY	11	6	5
104C	28	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1999	SATISFACTORY	11	6	5
105	100	817	STUDENT RESTROOM & BATH	0	01	CERAMIC TILE	1999	SATISFACTORY	11	6	5
106	100	811	OUTSIDE STORAGE	0	01	CONCRETE	1999	SATISFACTORY	11	6	5
107	950	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1999	SATISFACTORY	11	6	5
107A	155	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1999	SATISFACTORY	11	6	5
107B	40	813	STUDENT STORAGE	0	01	COMPOSITION TILE	1999	SATISFACTORY	11	6	5
107C	28	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1999	SATISFACTORY	11	6	5
108	96	702	MECHANICAL ROOM	0	01	CONCRETE	1999	SATISFACTORY	11	6	5
109	48	702	MECHANICAL ROOM	0	01	CONCRETE	1999	SATISFACTORY	11	6	5
110	48	702	MECHANICAL ROOM	0	01	CONCRETE	1999	SATISFACTORY	11	6	5
111	2120	701	COVERED WALKWAY	0	01	CONCRETE	1999	SATISFACTORY	11	6	5



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	9,339	54	0	0				
TOTAL	9,339	54	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 12 - Building Number 00012

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: NONE
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: NONE
Year Constructed: 1999	Artificial Lighting: GLOBE FIXTURE	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 1999	Intercom: NONE	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: NONE	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
100	121	333	FLAMMABLE STORAGE	0	01	CONCRETE	1999	SATISFACTORY	12	6	5

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	121	0	0	0				
TOTAL	121	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 13 - Building Number 00013

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: VACANT	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 2003	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: CLOSED CIRCUIT	Heat Capacity: ADEQUATE
Average Age NSF: 2003	Intercom: TWO WAY COMPLETE	Walls: COMBINATION OF 1-5
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
1301	642	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2003	SATISFACTORY	13	6	5
1302	931	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	2003	SATISFACTORY	13	6	5
1302A	43	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	2003	SATISFACTORY	13	6	5
1302B	88	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	2003	SATISFACTORY	13	6	5
1302C	102	315	TEACHER PLANNING OFFICE	0	01	COMPOSITION TILE	2003	SATISFACTORY	13	6	5
1303	37	331	CUSTODIAL SERVICE CLOSET	0	01	CONCRETE	2003	SATISFACTORY	13	6	5
1304	931	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	2003	SATISFACTORY	13	6	5
1304A	43	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	2003	SATISFACTORY	13	6	5
1304B	88	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	2003	SATISFACTORY	13	6	5
1304C	102	315	TEACHER PLANNING OFFICE	0	01	COMPOSITION TILE	2003	SATISFACTORY	13	6	5
1305	23	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	01	CONCRETE	2003	SATISFACTORY	13	6	5



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 13 - Building Number 00013

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
1306	24	703	ELECTRICAL ROOM	0	01	CONCRETE	2003	SATISFACTORY	13	6	5
1307	50	702	MECHANICAL ROOM	0	01	CONCRETE	2003	SATISFACTORY	13	6	5
1308	635	316	TEACHER LOUNGE/DINING	0	01	COMPOSITION TILE	2003	SATISFACTORY	13	6	5
1308A	43	821	STAFF RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	2003	SATISFACTORY	13	6	5
1309	133	303	SECRETARIAL SPACE	0	01	CARPET	2003	SATISFACTORY	13	6	5
1309A	43	309	VAULT/STUDENT RECORDS	0	01	COMPOSITION TILE	2003	SATISFACTORY	13	6	5
1310	137	303	SECRETARIAL SPACE	0	01	CARPET	2003	SATISFACTORY	13	6	5
1310A	43	309	VAULT/STUDENT RECORDS	0	01	COMPOSITION TILE	2003	SATISFACTORY	13	6	5
1311	173	301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	01	CARPET	2003	SATISFACTORY	13	6	5
1312	185	306	CONFERENCE ROOM	0	01	CARPET	2003	SATISFACTORY	13	6	5
1313	43	822	PUBLIC USE RESTROOM (MALE)	0	01	CERAMIC TILE	2003	SATISFACTORY	13	6	5
1314	43	823	PUBLIC USE RESTROOM (FEMALE)	0	01	CERAMIC TILE	2003	SATISFACTORY	13	6	5
1315	260	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2003	SATISFACTORY	13	6	5
1316	320	701	COVERED WALKWAY	0	01	CONCRETE	2003	SATISFACTORY	13	6	5

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	5,162	36	0	0				
TOTAL	5,162	36	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 14 - MULTI PURPOSE

Owner: SCHOOL BOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 2013	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 2013	Intercom: TWO WAY COMPLETE	Walls: BRICK
Relocatable Units: 0	Telephone: COMPLETE TO ALL ROOMS	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: SINGLE INSIDE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
1461	2084	361	MULTIPURPOSE ROOM (DINING)	0	01	COMPOSITION TILE	2013	SATISFACTORY	14	6	5
1462	116	362	MULTIPURPOSE ROOM CHAIR STORAGE	0	01	COMPOSITION TILE	2013	SATISFACTORY	14	6	5
1463	825	363	STAGE	0	01	WOOD	2013	SATISFACTORY	14	6	5
1464	302	364	STAGE STORAGE	0	01	COMPOSITION TILE	2013	SATISFACTORY	14	6	5
1465	164	365	STAGE DRESSING ROOM (MALE)	0	01	COMPOSITION TILE	2013	SATISFACTORY	14	6	5
1466	152	366	STAGE DRESSING ROOM (FEMALE)	0	01	COMPOSITION TILE	2013	SATISFACTORY	14	6	5
1467	97	707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	01	COMPOSITION TILE	2013	SATISFACTORY	14	6	5



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 14 - MULTI PURPOSE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
1468	139	822	PUBLIC USE RESTROOM (MALE)	0	01	CERAMIC TILE	2013	SATISFACTORY	14	6	5
1469	139	823	PUBLIC USE RESTROOM (FEMALE)	0	01	CERAMIC TILE	2013	SATISFACTORY	14	6	5
1470	220	370	LOBBY	0	01	COMPOSITION TILE	2013	SATISFACTORY	14	6	5
1471	579	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	2013	SATISFACTORY	14	6	5
1472	53	331	CUSTODIAL SERVICE CLOSET	0	01	COMPOSITION TILE	2013	SATISFACTORY	14	6	5
1473	67	703	ELECTRICAL ROOM	0	01	COMPOSITION TILE	2013	SATISFACTORY	14	6	5
1474	149	702	MECHANICAL ROOM	0	01	CONCRETE	2013	SATISFACTORY	14	6	5

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Permanent	5,086	0	0	0				
TOTAL	5,086	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 100 - MODULAR

Owner: LEASE PURCHASE	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 2006	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: INDIVIDUAL UNIT REVERSE CYCLE
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 2013	Intercom: ONE WAY COMPLETE	Walls: FACTORY BUILT
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: RECONSTRUCTABLE CONCRETE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
563	864	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	2011	SATISFACTORY	100	6	5
564	42	814	STUDENT RESTROOM (BOTH SEXES)	0	01	OTHER	2011	SATISFACTORY	100	6	5
565	864	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	2011	SATISFACTORY	100	6	5
566	42	814	STUDENT RESTROOM (BOTH SEXES)	0	01	OTHER	2011	SATISFACTORY	100	6	5
567	864	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	2011	SATISFACTORY	100	6	5
568	42	814	STUDENT RESTROOM (BOTH SEXES)	0	01	OTHER	2011	SATISFACTORY	100	6	5
569	864	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	2011	SATISFACTORY	100	6	5
570	42	814	STUDENT RESTROOM (BOTH SEXES)	0	01	OTHER	2011	SATISFACTORY	100	6	5



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 3 BAY COUNTY SCHOOL DISTRICT

FACILITY: 5-A CALLAWAY ELEMENTARY

BUILDING: 100 - MODULAR

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	STU STA	FLR LOC	FLOOR COVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
571	864	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	2011	SATISFACTORY	100	6	5
572	42	814	STUDENT RESTROOM (BOTH SEXES)	0	01	OTHER	2011	SATISFACTORY	100	6	5
573	864	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	2011	SATISFACTORY	100	6	5
574	42	814	STUDENT RESTROOM (BOTH SEXES)	0	01	OTHER	2011	SATISFACTORY	100	6	5
575	864	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	2011	SATISFACTORY	100	6	5
576	42	814	STUDENT RESTROOM (BOTH SEXES)	0	01	OTHER	2011	SATISFACTORY	100	6	5
577	864	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	2011	SATISFACTORY	100	6	5
578	42	814	STUDENT RESTROOM (BOTH SEXES)	0	01	OTHER	2011	SATISFACTORY	100	6	5
579	864	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	2018	SATISFACTORY	100	6	5
580	864	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	2018	SATISFACTORY	100	6	5
581	864	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	2018	SATISFACTORY	100	6	5
582	864	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	2018	SATISFACTORY	100	6	5
583	864	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	2018	SATISFACTORY	100	6	5
584	864	2	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	22	01	COMPOSITION TILE	2018	SATISFACTORY	100	6	5

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations
Modular	12,432	276	0	0				
TOTAL	12,432	276	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

STUDENT STATIONS BY DESIGN CODE FOR:

FACILITY: CALLAWAY ELEMENTARY

Design Code	Design Code Description	Satis Stu Sta			Unsat Stu Sta			Sat	Unsat	Satis Rooms			Unsatis Rooms			Fail Std Stu Sta	Repl Stu Sta	Fail Std Rooms	Repl Rooms
		Perm	Mod	Relo	Perm	Mod	Relo	Tot	Tot	Perm	Mod	Relo	Perm	Mod	Relo	Relo	Relo	Relo	Relo
00001	PRIMARY CLASSROOM (K-3)	414	144	0	0	0	0	558	0	23	8	0	0	0	0	0	0	0	0
00002	INTERMEDIATE/MIDDLE CLASSROOM (4-8)	198	132	0	0	0	0	330	0	9	6	0	0	0	0	0	0	0	0
00013	ELEMENTARY P E STORAGE	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	0
00040	RESOURCE ROOM	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	0
00050	ART - ELEMENTARY	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00055	MUSIC - ELEMENTARY	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00062	E S E FULL-TIME	10	0	0	0	0	0	10	0	1	0	0	0	0	0	0	0	0	0
00121	OTHER P E SPACE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00300	PRINCIPAL/DIRECTOR OFFICE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00301	ASSISTANT PRINCIPAL/OTHER OFFICE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00302	BOOKKEEPING OFFICE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00303	SECRETARIAL SPACE	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	0
00304	RECEPTION AREA	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00306	CONFERENCE ROOM	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00307	CLINIC	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00308	GENERAL SCHOOL STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00309	VAULT/STUDENT RECORDS	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	0
00314	ITINERANT OFFICE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00315	TEACHER PLANNING OFFICE	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	0
00316	TEACHER LOUNGE/DINING	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	0
00317	GENERAL SCHOOL SPACE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00331	CUSTODIAL SERVICE CLOSET	0	0	0	0	0	0	0	0	4	0	0	0	0	0	0	0	0	0
00333	FLAMMABLE STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00340	DINING AREA	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

STUDENT STATIONS BY DESIGN CODE FOR:

FACILITY: CALLAWAY ELEMENTARY

Design Code	Design Code Description	Satis Stu Sta			Unsat Stu Sta			Sat Tot	Unsat Tot	Satis Rooms			Unsatis Rooms			Fail Std Stu Sta	Repl Stu Sta	Fail Std Rooms	Repl Rooms
		Perm	Mod	Relo	Perm	Mod	Relo			Perm	Mod	Relo	Perm	Mod	Relo	Relo	Relo	Relo	Relo
00342	KITCHEN DRY STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00343	KITCHEN OFFICE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00346	KITCHEN FOOD PREPARATION	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00350	OTHER FOOD SERVICE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00361	MULTIPURPOSE ROOM (DINING)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00362	MULTIPURPOSE ROOM CHAIR STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00363	STAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00364	STAGE STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00365	STAGE DRESSING ROOM (MALE)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00366	STAGE DRESSING ROOM (FEMALE)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00370	LOBBY	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00380	LIBRARY (READING ROOM/STACKS)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00383	AUDIO VISUAL STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00387	MEDIA PRODUCTION LAB	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00700	INSIDE CIRCULATION	0	0	0	0	0	0	0	0	7	0	0	0	0	0	0	0	0	0
00701	COVERED WALKWAY	0	0	0	0	0	0	0	0	7	0	0	0	0	0	0	0	0	0
00702	MECHANICAL ROOM	0	0	0	0	0	0	0	0	30	0	0	0	0	0	0	0	0	0
00703	ELECTRICAL ROOM	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	0
00707	TELEPHONE EQUIPMENT/COMMUNICATION CLOSET	0	0	0	0	0	0	0	0	4	0	0	0	0	0	0	0	0	0
00805	KILN	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00806	REFERENCE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00808	MATERIAL STORAGE	0	0	0	0	0	0	0	0	26	0	0	0	0	0	0	0	0	0
00811	OUTSIDE STORAGE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

STUDENT STATIONS BY DESIGN CODE FOR:

FACILITY: CALLAWAY ELEMENTARY

Design Code	Design Code Description	Satis Stu Sta			Unsat Stu Sta			Sat	Unsat	Satis Rooms			Unsatis Rooms			Fail Std Stu Sta	Repl Stu Sta	Fail Std Rooms	Repl Rooms
		Perm	Mod	Relo	Perm	Mod	Relo	Tot	Tot	Perm	Mod	Relo	Perm	Mod	Relo	Relo	Relo	Relo	Relo
00812	PROJECT STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00813	STUDENT STORAGE	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	0
00814	STUDENT RESTROOM (BOTH SEXES)	0	0	0	0	0	0	0	0	24	8	0	0	0	0	0	0	0	0
00815	STUDENT RESTROOM (MALE)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00816	STUDENT RESTROOM (FEMALE)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00817	STUDENT RESTROOM & BATH	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00819	STAFF RESTROOM (MALE)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00820	STAFF RESTROOM (FEMALE)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00821	STAFF RESTROOM (BOTH SEXES)	0	0	0	0	0	0	0	0	5	0	0	0	0	0	0	0	0	0
00822	PUBLIC USE RESTROOM (MALE)	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00823	PUBLIC USE RESTROOM (FEMALE)	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00831	MUSIC PRACTICE ROOM	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
Totals:		622	276	0	0	0	0	898	0	213	22	0	0	0	0	0	0	0	0